
Technical Information

Service
8/08 ENU 1901

1

Aug 14, 2018

Engine Oil In Cooling System (8/08)

Model year: **as of 1997**

Revision:

This bulletin replaces bulletin dated March 17, 2008.

This revision includes additional vehicle types.

Model Line:

Cayenne

Panamera

Macan

911

Boxster/Cayman

Subject:

Cleaning cooling system.

Information:

Engine oil in cooling system (coolant warning light comes on).

Due to the fact that engines have been replaced unnecessarily in the dealer organization, we must point out that the cooling system must be cleaned as described in the Workshop Manual and using the cleaning agent → 000.043.204.39 after engine oil is found in the cooling system and after the required repairs have been performed. See [→ 190129 Cleaning the cooling system \(after oil and coolant mix\)](#).

Parts Info:

000.043.204.39 → Cleaning agent

References:

[→ 190101 Checking the cooling system](#)

[→ 190129 Cleaning the cooling system \(after oil and coolant mix\)](#)